



UNICAN AS OF VERSION 1.12

SERWIS.PL AUTOMOTIVE SOLUTIONS

As of v1.12, an additional emulator program selection has been added using the setting the program number at address 0x02 in the EEPROM 24c02 I2C mounted on the emulator PCB.

Current program numbers:

- Value 0xFF - All legacy programs except the WFS5/PQ35 MQB TCU.
- Value 0x01 - ECU and TCU VAG WFS5/PQ35 and part of MQB.
- Value 0x02 - ECU SMART FORTWO/SMART FORFOUR GEN 1/MITSUBISHI COLT Z30 CZC.
- Value 0x03 - ECU BMW EWS4 (SWAP ENGINE).
- Value 0x04 - TCU BMW EWS4 (SWAP GEARBOX).

ADDRESS
FOR PROGRAM
CHANGE 0x02

Offset (h)	00	01	02	03	04	05	06	07	08	09	0A	0B	0C	0D	0E	0F
00000000	FF	50	01	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF
00000010	FD	3D	BB	85	DA	6D	8C	48	75	54	C6	44	E5	58	10	15
00000020	03	E1	4F	C2	12	CA	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF
00000030	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF
00000040	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF
00000050	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF
00000060	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF
00000070	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF
00000080	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF
00000090	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF
000000A0	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF
000000B0	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF
000000C0	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF
000000D0	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF
000000E0	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF
000000F0	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF	FF

ALL TECHNICAL ISSUES PLEASE CONTACT OVER THE COMPANY E-MAIL :
ecuserwis@ecuserwis.pl